### MONTANA STATE AVIATION SYSTEM PLAN 1995 UPDATE FIELD INSPECTION FORM

AIRPORT:	BOWMAN FIELD (3U3)	AIRPORT REFERENCE CODE:	B-I (SM)
CITY:	ANACONDA	APPROACH TYPE:	BASIC
CONTACT:	JOHN McPHAIL	DATE INVENTORIED:	1-11-96
PHONE #:	563-8275	INSPECTED BY:	RSD

	REQUIRED	ACTUAL	ALP	CONFORM
RUNWAY 4/22 INVENTORY				
DISTANCE TO:				
HOLD LINES FROM CENTERLINE:	125'	130' & 200'		✓
PARALLEL TAXIWAY FROM CENTERLINE:	150'	458' & 485'		✓
AIRCRAFT PARKING FROM CENTERLINE:	125'	285'		✓
RUNWAY WIDTH:	60'	60'		✓
RUNWAY LENGTH:	6,080' (1)		4,520'	75%
RUNWAY SAFETY AREA (RSA) WIDTH:	120'	OK		✓
RUNWAY OBJECT FREE AREA (OFA) WIDTH:	250'	OK		✓
PRIMARY / TRANSITION SURFACE PENETRATIONS:	250' W & 7:1	(2),(3) &(4)		NO
LONGITUDINAL GRADE - SITE DIST. PROBLEMS:		OK		✓
OBSTACLE FREE ZONE ANALYSIS:	250' WIDE x 200	0' BEYOND		(3)
PAVEMENT EDGE LIP HEIGHT (MIN AND MAX):	1.5" - 3"	1"-2"		<b>√</b>
PAVEMENT MARKING TYPE:	BASIC	BASIC		✓
PAVEMENT MARKING CONDITION:		FAIR		N/A
RUNWAY 4 END INVENTORY				
SAFETY AREA (RSA) BEYOND RUNWAY END:	240'	ОК		/
OBJECT FREE AREA (OFA) BEYOND RUNWAY END:	240'	OK		/
APPROACH OBSTRUCTIONS:	20:1	(5)		OK
RUNWAY END ELEVATION:	20.1	(5)	5,030.6	N/A
KUNWAT END ELEVATION.			5,030.6	IN/A
RUNWAY22_ END INVENTORY				
SAFETY AREA (RSA) BEYOND RUNWAY END:	240'	OK		✓
OBJECT FREE AREA (OFA) BEYOND RUNWAY END:	240'	(3)		NO
APPROACH OBSTRUCTIONS:	20:1	NONE		✓
RUNWAY END ELEVATION:			4,985.2	N/A
RUNWAY LIGHTING INVENTORY				
DISTANCE FROM PAVEMENT EDGE:	10'	10'		/
MAXIMUM DISTANCE BETWEEN LIGHTS:	200'	200'		/
TYPE:		MOUNTED - NATI	ONAL	N/A
CONDITION:	WIIKE - STAKE I	GOOD	ONAL	N/A
COLOR:	WHITE	WHITE		N/A ✓
	VVI II I L	VVI II I L		
THRESHOLD 4				
DISTANCE FROM PAVEMENT EDGE:	10'	13'		NO
MAXIMUM DISTANCE BETWEEN LIGHTS:	10'	10		✓
COLOR:	RED/GREEN	RED/GREEN		✓
THRESHOLD 22				
DISTANCE FROM PAVEMENT EDGE:	10'	10'		/
MAXIMUM DISTANCE BETWEEN LIGHTS:	10'	10'		/
COLOR:	RED/GREEN	RED/GREEN		/
	LD, OILLIN	TILD, SILLEN		•

# COMMENTS:

- (1) RW LENGHT OF 4,420' FOR 75%, 5,900' FOR 95%, AND 6,080 FOR 100% COVERAGE; ALP ULTIMATE SHOWN AS 6,000' (80% OF PRIMARY RUNWAY LENGTH IS 4,800' DOES NOT COMPLY)
- (2) OLD WINDSOCK HARDWARE ON T-HANGAR BY 4 END IN TRANSITIONAL SURFACE (16%)
- (3) 6' HIGH SMALL BRUSH IN PRIMARY SURFACE ON CL 177' FROM END
- (4) 5' AND LESS HIGH SMALL BRUSH 125' OFF CL ON E. SIDE, ON W. SIDE (2) AT 25% & (1) IN PRIMARY SURFACE
- (5) POWER POLES AT 5%

#### MONTANA STATE AVIATION SYSTEM PLAN 1995 UPDATE FIELD INSPECTION FORM

AIRPORT:	BOWMAN FIELD (3U3)	AIRPORT REFERENCE CODE:	B-II (SM)
CITY:	ANACONDA	APPROACH TYPE:	NPI
CONTACT:	JOHN McPHAIL	DATE INVENTORIED:	1-11-96
PHONE #:	563-8275	INSPECTED BY:	RSD

	REQUIRED	ACTUAL	ALP	CONFORM
RUNWAY 16/34 INVENTORY		7.70.7.07.1		00111011111
DISTANCE TO:				
HOLD LINES FROM CENTERLINE:	125'	200'		✓
PARALLEL TAXIWAY FROM CENTERLINE:	240'	N/A		N/A
AIRCRAFT PARKING FROM CENTERLINE:	250'	N/A		N/A
RUNWAY WIDTH:	75'	75'		
RUNWAY LENGTH:	6,080' (1)	70	6.000'	95%
RUNWAY SAFETY AREA (RSA) WIDTH:	150'	ОК	0,000	<b>1</b>
RUNWAY OBJECT FREE AREA (OFA) WIDTH:	500'	(2)		NO
PRIMARY / TRANSITION SURFACE PENETRATIONS:	500' W & 7:1	(3) & (4)		NO
LONGITUDINAL GRADE - SITE DIST. PROBLEMS:	300 W & 7.1	OK		<b>₩</b>
OBSTACLE FREE ZONE ANALYSIS:	250' WIDE x 20	1		(3)
PAVEMENT EDGE LIP HEIGHT (MIN AND MAX):	1.5" - 3"	FLUSH - 1"		OK OK
PAVEMENT MARKING TYPE:	NPI	NPI		or ✓
PAVEMENT MARKING CONDITION:	INFI	POOR		N/A
PAVEIVIENT MARKING CONDITION.		POOR		IN/A
RUNWAY 16 END INVENTORY				
SAFETY AREA (RSA) BEYOND RUNWAY END:	300'	OK		
OBJECT FREE AREA (OFA) BEYOND RUNWAY END:	300'	OK		/
APPROACH OBSTRUCTIONS:	20:1	NONE		/
RUNWAY END ELEVATION:			4,994.3	N/A
DUNINANA OA ENDUNINENTODY				
RUNWAY 34 END INVENTORY	0001	014		
SAFETY AREA (RSA) BEYOND RUNWAY END:	300'	OK		<b>/</b>
OBJECT FREE AREA (OFA) BEYOND RUNWAY END:	300'	OK (5)		/
APPROACH OBSTRUCTIONS:	20:1	(5)	F 000 F	<b>√</b>
RUNWAY END ELEVATION:			5,028.5	N/A
RUNWAY LIGHTING INVENTORY				
DISTANCE FROM PAVEMENT EDGE:	10'	10'		
MAXIMUM DISTANCE BETWEEN LIGHTS:	200'	(6)		/
TYPE:		MOUNTED - ADB	-ALNACO	N/A
CONDITION:	IVIII CE OTTUCE	GOOD (6)		N/A
COLOR:	WHITE	WHITE		\ \frac{1000}{1000}
	VVI II I L	VVI II I L		
THRESHOLD 16				
DISTANCE FROM PAVEMENT EDGE:	10'	10'		<b>│</b>
MAXIMUM DISTANCE BETWEEN LIGHTS:	10'	10		✓
COLOR:	RED/GREEN	RED/GREEN		<b>│</b>
THRESHOLD 34				
DISTANCE FROM PAVEMENT EDGE:	10'	10'		/
MAXIMUM DISTANCE BETWEEN LIGHTS:	10'	10'		/
COLOR:	RED/GREEN	RED/GREEN		
002011.	KLD/OKLLIN	INLD/ONLLIN		•

# COMMENTS:

- $(1) \ RW \ LENGTH \ OF \ 4,420' \ FOR \ 75\%, \ 5,900' \ FOR \ 95\%, \ AND \ 6,080 \ FOR \ 100\% \ COVERAGE; \ ALP \ ULTIMATE \ SHOWN \ AS \ 6,000' \ AND \ 6$
- (2)SMALL BRUSH IN OFA 200' FROM CL AND SLIGHTLY NORTH OF TAXIWAY
- (3) TREES ALONG WEST FENCE PENETRATE TRANSITIONAL SURFACE, 50% AND 35%
- (4) WIND SOCK AT NORTH END NEAR EAST FENCE PENETRATES TRANSITIONAL SURFACE AT 50%
- (5) TREES LEFT AND RIGHT OF APPROACH AT 5% PER ALP JUST OUTSIDE RPZ BOUNDARY
- (6) EIGHT KNOCKED DOWN OR MISSING LIGHTS, TWO MISSING GLOBES; MOSTLY ON EAST SIDE OF RUNWAY

### MONTANA STATE AVIATION SYSTEM PLAN 1995 UPDATE FIELD INSPECTION FORM

AIRPORT:	BOWMAN FIELD (3U3)	AIRPORT REFERENCE CODE:	B-II (SM)
CITY:	ANACONDA	APPROACH TYPE:	NPI
CONTACT:	JOHN McPHAIL	DATE INVENTORIED:	1-11-96
PHONE #:	563-8275	INSPECTED BY:	RSD

	REQUIRED		ACTUAL	ALP	CONFORM
TAXIWAY INVENTORY					
TAXIWAY WIDTH:	35'		25' & 37'		NO
TAXIWAY SAFETY AREA WIDTH:	79'		OK		✓
TAXIWAY OBJECT FREE AREA WIDTH:	131'		OK		1
DIST. FROM CENTERLINE TO FIXED OR MOVEABLE OBJ.	65.5'		OK		✓
PAVEMENT EDGE LIP HEIGHT (MIN AND MAX):	1.5" - 3"		1"		OK
PAVEMENT MARKING TYPE:			YELLOW		✓
PAVEMENT MARKING CONDITION:			GOOD		N/A
TAXIWAY LIGHTING INVENTORY			(1)		
DISTANCE FROM PAVEMENT EDGE:	10'		10'		<b>✓</b>
MAXIMUM DISTANCE BETWEEN LIGHTS:	200'		200'		✓
TYPE:		RI	EFLECTORS		N/A
CONDITION:			GOOD		N/A
COLOR:	BLUE		BLUE		✓

MISCELLANEOUS	
TYPE OF BEACON:	MOUNTED ON 50' METAL TOWER SW OF APRON AREA
SIZE OF BEACON:	12"
OILL OF BLACOTT.	
OTHER LIGHTING AIDS (VASI,PAPI,REIL):	4,16,&34 ENDS: ADB-ALNACO 2-BOX PAPI, GOOD COND,
<b>,</b> , ,	50' OFF PVMT
WINDCONE (CONDITION & COMPLIANCE):	MID-FIELD, SW OF TAXIWAY, LIGHTED, 25', GOOD COND
SEGMENTED CIRCLE (CONDITION & COMPLIANCE):	METAL PANEL SEGMENTED CIRCLE IN GOOD CONDITION
MINDOONE (OONDITION & OONDI MANOE)	
WINDCONE (CONDITION & COMPLIANCE):	EAST OF 16 END, ALONG FENCE, UNLIGHTED,
OFOMENITED OUDOLE (OONDITION & OOMBLIANOE)	25' HIGH IN GOOD COND
SEGMENTED CIRCLE (CONDITION & COMPLIANCE):	NONE
FENCING:	GOOD
1 2.10.110.	0000
SIGNS: (TYPE, CONDITION, PLACEMENT)	FOUR DIRECTIONAL SIGNS, THREE ON TAXIWAY, ONE AT 4 END
( ,	THREE 15' OFF PVMT ONE 12' OFF PVMT

ALL LUMACURVE IN GOOD COND

COMMENTS:
(1) ENTRANCE BLUE LIGHTS ON RUNWAY ONTO ALL TAXIWAYS - NONE FOR JUGHANDLES THOUGH
(BLUE REFLECTORS ON ALL TAXIWAYS BUT NONE ON JUGHANDLES)